

# Installation of shaft seal on crankshaft

## 340.920


Suitable for AUDI | MAN | SEAT | SKODA | VW

Localised leakage may occur at the plastic housing of the radial shaft seal on Euro 6 vehicles of the VW Group equipped with 1.6- or 2.0-liter TDI EA288 engines from model year 2012 onwards.

Elring supplies the radial shaft seal with housing. Installation is performed from the front. To prevent leaks or damage, the following steps must be observed.



- 
- 
- 
- 
- 
- 
- 
- 
- 



340.290



919.411 | 896.341



YouTube

